

DTC	P1346/18	VVT Sensor/Camshaft Position Sensor Circuit Range/Performance Problem (Bank 1)
------------	-----------------	---

DTC	P1351/18	VVT Sensor/Camshaft Position Sensor Circuit Range/Performance Problem (Bank 2)
------------	-----------------	---

CIRCUIT DESCRIPTION

Refer to DTCs P1345/18 and P1350/18 on page DI-125.

DTC No.	Detection Item	Trouble Area
P1346/18	Deviation in crankshaft position sensor signal and VVT sensor 1 signal (2-trip detection logic)	<ul style="list-style-type: none"> Mechanical system (Jumping teeth of timing belt, belt stretched)
P1351/18	Deviation in crankshaft position sensor signal and VVT sensor 2 signal (2-trip detection logic)	<ul style="list-style-type: none"> ECM

WIRING DIAGRAM

Refer to DTCs P1345/18 and P1350/18 on page DI-125.

INSPECTION PROCEDURE

HINT:

Read freeze frame data using hand-held tester. Because freeze frame records the engine conditions when the malfunction is detected. When troubleshooting, it is useful for determining whether the vehicle was running or stopped, the engine was warmed up or not, the air-fuel ratio was lean or rich, etc. at the time of the malfunction.

1	Check valve timing (Check for loose and jumping teeth of timing belt) (See page EM-26).
---	--

NG

Adjust valve timing (Repair or replace timing belt).

OK

Check and replace ECM (See page IN-35).