

DTC	B1216	Rear right door ECU communication stop
------------	--------------	---

CIRCUIT DESCRIPTION

This DTC is output when communication stops between the rear door RH ECU and the gateway ECU.

DTC No.	DTC Detecting Condition	Trouble Area
B1216	No communication from rear door right ECU for more than 10 seconds.	<ul style="list-style-type: none"> •Rear door RH ECU •Wire harness

WIRING DIAGRAM

See [page DI-1482](#).

INSPECTION PROCEDURE

1	Check rear door RH ECU.
----------	--------------------------------

CHECK:

Check if the rear door right window glass automatically moves up.

HINT:

With this inspection, whether or not the rear door RH ECU functions normally can be diagnosed.




2 Check wire harness.**PREPARATION:**

Pull out the ECU connectors mentioned below.

Wire harness side connector of ECU	Terminal
Rear door RH ECU – Front passenger door ECU	MPX1 (R15–18) – MPX2 (F17–26)
Rear door RH ECU – Rear door LH ECU	MPX2 (R15–20) – MPX1 (R16–18)

CHECK:

Check continuity of the wire harness between the connectors.

**OK:**

There is a continuity between the connectors.

HINT:

If there is OPEN in any wire harness, please repair it.

NG**Repair or replace wire harness.****OK**

Replace rear door RH ECU (See page IN-35).