


2. Layout of Main Component



259LSK61

3. Diagnosis

DTC (Diagnostic Trouble Code) has been discontinued.

► Discontinued DTC ◀

DTC No.		Detection Item
2-digit	5-digit	
—	C1560	Malfunction in PPS solenoid circuit
—	C1561	