DI8RG-01

6. Radio broadcast cannot be received. (Bad reception)



1 Is this condition worse in comparison with other vehicle?

Yes

Receiving environment is bad.

No

2 Are there any parts installed, additionelly? (Sunshade film, telephone antenna, etc.)

Yes

Does the condition get better if removing them? Influence of those parts.

No

Check if there is any scratch and breaking of a wire for glass antenna and defogger pattern. (Visual check)

Yes<u>□</u>

Repair See page BE-82).

No

4 Is contact of radio plug jack OK?

No

Take measures for contact.

Yes

5[]	Is[antenna[terminal[on[glass[surface[in[contact[with[defogger[terminal?
	No Take measures for contact.
Yes	
6	Isြcontinuity[of[antennaြcord[OK?
	No ☐ Replace antenna cord.
Yes	
7	Check@rounding@f@antenna,@antenna@cord@and@noise@ilter.
	NG Grounding failure.
ОК	
8[]	Does@condition@get@better@by@replacing@antenna@cord?
	Yes ☐ Replace antenna cord.
No	
Repla BO-1	ce[rear[window[glass[(See[page